

SANTI GULLY

GULLY STABILIZATION



Neighbors on South Center Lake came to the Chisago Soil & Water Conservation District (SWCD) with an eroding gully on their property line in the spring of 2019. The SWCD assessed the gully and determined the best way to keep sediment out of the lake was to install a rate control pipe to carry the water down the steep slope safely. The hillside is also now stabilized with native plants.



Partners:

John & Colleen Santi
Brian & Gina Johnsen
Chisago Lakes Lake Improvement District
Chisago SWCD

Pollution Reduction:

TSS: 1.7 tons/yr
TP: 1.7 lbs/yr
(Board of Water & Soil Resources (BWSR) Spreadsheet)

Targeted Water:

South Center Lake

Completion Date:

October 2019

May I Visit?

No – This project is completely on private property.

